1 00:00:00.000 --> 00:00:01.820 And I asked Ray, so you've got his bio here again. 2 00:00:01.820 --> 00:00:03.045 And I asked him, Hey, is there anything, 3 00:00:03.165 --> 00:00:05.445 'cause I don't know him, I, I asked there anything specific 4 00:00:05.625 --> 00:00:07.805 you want me to highlight in your bio? 5 00:00:08.225 --> 00:00:10.365 And he said, just tell people that I'm the chief 6 00:00:10.365 --> 00:00:11.365 of safety at Edwards 7 00:00:11.385 --> 00:00:13.245 and I've been doing safety for a long time. 8 00:00:13.865 --> 00:00:15.365 So, okay. So that's, that's it. 9 00:00:15.365 --> 00:00:16.445 I'll leave that as the introduction, 10 00:00:16.445 --> 00:00:17.485 but I do want to say this. 11 00:00:18.065 --> 00:00:21.825 So you see the title of what he's going to talk about. 12 00:00:22.565 --> 00:00:26.395 I will tell you, this is, this is my fifth one 13 00:00:26.395 --> 00:00:27.955 of these as chairman.

WEBVTT

14 00:00:28.665 --> 00:00:32.205 Um, it's hard to get people to come present 15 00:00:32.425 --> 00:00:34.405 for a variety of reasons. 16 00:00:35.115 --> 00:00:38.785 It is the most difficult to get people 17 00:00:39.045 --> 00:00:41.745 to come talk about accidents. 18 00:00:42.325 --> 00:00:45.105 So when Ray offered this up, Hey, 19 00:00:45.185 --> 00:00:47.465 I can come talk about an accident that happened. 20 00:00:47.615 --> 00:00:50.265 There's no way we weren't gonna get him on the docket. 21 00:00:50.365 --> 00:00:53.305 So with that said, Mr. Quez podium is yours. 22 00:01:02.535 --> 00:01:03.555 Uh, where's the clicker? 23 00:01:09.105 --> 00:01:09.685 All the sugar. 24 00:01:15.465 --> 00:01:20.305 So, um, first of all, um, this is a sad topic and, 25 00:01:20.405 --> 00:01:23.225 and I apologize for, uh, being the last presenter for this. 2.6 00:01:23.485 --> 00:01:27.335 Um, but, uh, this does happen in our line of business, 27 00:01:27.335 --> 00:01:28.575

and so we should learn from it. 28 00:01:29.405 --> 00:01:32.925 Um, the ideas presented that you heard about this morning, 29 00:01:33.265 --> 00:01:36.615 um, turbo talked about visual learning. 30 00:01:37.355 --> 00:01:42.235 Um, Roy talked about the, uh, comp plan, uh, 31 00:01:42.755 --> 00:01:43.955 pressure, pressure from programs 32 00:01:43.955 --> 00:01:45.395 and the importance of training. 33 00:01:46.555 --> 00:01:49.055 And then David talked about, uh, the idea 34 00:01:49.075 --> 00:01:51.695 of people being comfortable and speaking up, 35 00:01:52.155 --> 00:01:53.935 and that, uh, everybody on the team 36 00:01:54.455 --> 00:01:55.835 should all be on the same page. 37 00:01:55.845 --> 00:01:59.225 These are all elements that you'll, uh, you'll pick up on 38 00:01:59.285 --> 00:02:01.105 as I brief this, uh, this accident. 39 00:02:03.415 --> 00:02:05.475 Uh, before I begin though, I would just want to emphasize 40 00:02:05.475 --> 00:02:10.195 that all the information from from this briefing are from

41 00:02:10.915 --> 00:02:13.155 publicly available documents, primarily from the 42 00:02:13.875 --> 00:02:15.515 accident investigation board report, 43 00:02:16.035 --> 00:02:18.305 which comes from a legal investigation. 44 00:02:19.685 --> 00:02:22.215 None of the information here are from the, uh, 45 00:02:22.735 --> 00:02:24.015 separate safety investigation, 46 00:02:24.265 --> 00:02:26.135 which is not publicly available. 47 00:02:27.375 --> 00:02:30.275 But as you'll see, there are many safety lessons 48 00:02:30.345 --> 00:02:34.435 that you can derive just from reading the A IB report. 49 00:02:40.855 --> 00:02:42.595 So on uh, September of last year, 50 00:02:43.455 --> 00:02:47.005 we had a civilian test engineer who was fatally injured 51 00:02:47.095 --> 00:02:50.325 after con, uh, walking into the propeller of a, 52 00:02:50.545 --> 00:02:53.405 of an MQ nine A aircraft during a ground test. 53 00:02:54.625 --> 00:02:56.845 Uh, for those of you who, who may be unfamiliar 54 00:02:56.845 --> 00:02:59.615

with the MQ nine Air MQ nine aircraft, 55 00:03:00.435 --> 00:03:02.815 it is a remotely piloted vehicle, uh, 56 00:03:02.825 --> 00:03:06.845 about 36 feet in length with a 66 foot wingspan 57 00:03:07.145 --> 00:03:11.385 and a height of 12 and a half feet has a single engine, uh, 58 00:03:11.385 --> 00:03:14.145 driving a single propeller, uh, attached 59 00:03:14.145 --> 00:03:15.505 to the Aden of the fuse lodge. 60 00:03:15.965 --> 00:03:20.915 So, as we go through the briefing, um, I ask you not 61 00:03:20.915 --> 00:03:22.955 to think about who is to blame for the mishap, 62 00:03:23.755 --> 00:03:25.175 but, uh, think about your test 63 00:03:25.275 --> 00:03:26.935 or test that you are reviewing 64 00:03:26.935 --> 00:03:30.355 or consulting with, uh, on things that you can do to change 65 00:03:30.355 --> 00:03:32.795 that test or reemphasize in your test operations 66 00:03:32.795 --> 00:03:35.035 to improve the safety of that, of that endeavor. 67 00:03:36.185 --> 00:03:39.865 Um, feel free to take notes on what, uh,

68 00:03:40.015 --> 00:03:41.105 what things you can change. 69 00:03:41.285 --> 00:03:43.345 And then, uh, I'll leave some time at the end for you 70 00:03:43.525 --> 00:03:46.265 to be able to share what you've, what you wrote down 71 00:03:46.265 --> 00:03:47.825 for the benefit of the rest of the audience. 72 00:03:51.265 --> 00:03:52.475 This is the order of the brief. 73 00:03:57.285 --> 00:03:59.675 These are the acronyms from the A IV report. 74 00:04:01.555 --> 00:04:04.135 Of note is the casualty, which I'll refer to as 75 00:04:05.575 --> 00:04:08.215 mishap test engineer one or MT one. 76 00:04:12.415 --> 00:04:14.715 So the accident happened in this airfield 77 00:04:15.055 --> 00:04:16.115 out in the Mojave Desert. 78 00:04:16.995 --> 00:04:20.955 Uh, it's, uh, surrounded by farmlands in the desert. 79 00:04:21.915 --> 00:04:25.725 It's a contractor owned, contractor controlled airfield. 80 00:04:26.715 --> 00:04:29.565 There's a small pre Air Force presence in the airfield, 81 00:04:29.575 --> 00:04:31.925

which is a detachment from the 82 00:04:32.465 --> 00:04:34.645 Air Force Lifecycle and Management Center. 83 00:04:35.295 --> 00:04:37.915 Uh, it's identified as detachment three or dead three. 84 00:04:42.375 --> 00:04:45.065 Just for perspective, the general map of the area, 85 00:04:45.445 --> 00:04:48.105 the airfield is located near the low right corner 86 00:04:48.125 --> 00:04:50.425 of this picture near El Mirage. 87 00:04:51.405 --> 00:04:54.985 It is about 30 miles away from Edwards is located 88 00:04:55.005 --> 00:04:59.795to the north, and also about 30 miles, uh, from Lancaster, 89 00:04:59.795 --> 00:05:01.595 the city of Lancaster, which is the, uh, 90 00:05:01.855 --> 00:05:04.675 the largest city in the valley over to the West. 91 00:05:10.405 --> 00:05:13.945 So before I discuss the test, it's worth discussing how, uh, 92 00:05:14.815 --> 00:05:18.535 operators and test personnel are warned about, uh, 93 00:05:18.955 --> 00:05:21.415 the danger of working when working around a, an, 94 00:05:21.435 --> 00:05:22.855 uh, a spinning propeller.

95 00:05:23.865 --> 00:05:25.885 So the A IB found four ways 96 00:05:25.995 --> 00:05:28.005 that personnel are educated about this. 97 00:05:29.225 --> 00:05:32.205 Uh, the first being the aircraft launch technical order, 98 00:05:32.225 --> 00:05:36.155 or geo, uh, where it describes the proper procedures 99 00:05:36.175 --> 00:05:38.155 for approaching an aircraft. 100 00:05:39.465 --> 00:05:44.205 Second is a, uh, new employee training brief offered 101 00:05:44.225 --> 00:05:46.325 by the, uh, detachment three. 102 00:05:47.225 --> 00:05:49.645 It contains a slide with danger areas regard 103 00:05:49.645 --> 00:05:51.165 regarding radiation zones 104 00:05:51.165 --> 00:05:52.885 and a, uh, propeller no entry zone. 105 00:05:54.445 --> 00:05:59.025 The third is a, uh, con contractor briefing on 106 00:05:59.025 --> 00:06:00.105 the safety and flight line. 107 00:06:00.205 --> 00:06:03.585 Basics, again, has a slide with the danger zones 108 00:06:03.585 --> 00:06:04.945

for radiation in the propeller. 109 00:06:06.255 --> 00:06:09.355 And then the fourth is this general maintenance procedure to 110 00:06:09.565 --> 00:06:13.035 where again, it depicts the area where you shouldn't enter 111 00:06:13.375 --> 00:06:15.155 or, uh, because of the, uh, propeller hazard. 112 00:06:18.765 --> 00:06:20.615 It's interesting to note that the, uh, 113 00:06:20.875 --> 00:06:24.535 propel propeller hazard areas from these three sources 114 00:06:25.285 --> 00:06:27.175 were very different in size and shape, 115 00:06:28.255 --> 00:06:32.875 and that the a IB was only able to confirm that MTE one 116 00:06:33.775 --> 00:06:36.275 saw the dead three slide, which had the smallest, 117 00:06:36.685 --> 00:06:38.405 which depicted the smallest, uh, 118 00:06:38.405 --> 00:06:40.045 hazard area out of the three. 119 00:06:46.595 --> 00:06:49.695 So the system under test was a government owned aircraft. 120 00:06:50.115 --> 00:06:52.015 It was being used for a series of ground 121 00:06:52.075 --> 00:06:54.845 and flight tests due to a new software.

122 00:06:56.565 --> 00:06:59.735 This particular test was an electromagnetic interference, 123 00:06:59.835 --> 00:07:04.275 electromagnetic compatibility ground test where, uh, 124 00:07:04.385 --> 00:07:07.515 telemetry readings were required from the weapons, uh, 125 00:07:07.515 --> 00:07:09.795 that were located on both the left and right wing. 126 00:07:13.305 --> 00:07:15.575 There were, um, several delays that occurred 127 00:07:15.575 --> 00:07:19.265 during the test program, uh, which, uh, delayed this, uh, 128 00:07:19.265 --> 00:07:21.585 completion of this ground test for a few weeks. 129 00:07:22.045 --> 00:07:25.265 So it is, it isn't hard to imagine that there was pressure 130 00:07:25.265 --> 00:07:27.625 to get this test done as soon as possible. 131 00:07:28.585 --> 00:07:29.965 And this was reflected 132 00:07:30.065 --> 00:07:33.165 by various comments from those on the test team obtained 133 00:07:33.185 --> 00:07:34.325 by the, by the board. 1.34 00:07:40.405 --> 00:07:42.425 The test team was made up of all contractors. 135 00:07:42.845 --> 00:07:45.585

You had, uh, an, the air crew composed of the pilot 136 00:07:45.645 --> 00:07:46.705 and the sensor operator. 137 00:07:47.535 --> 00:07:50.875 And, uh, mm, one is the crew chief, 138 00:07:51.885 --> 00:07:56.325 and all three have, uh, many years of experience on the, 139 00:07:56.345 --> 00:07:59.395 on the MQ nine, the, uh, 140 00:07:59.395 --> 00:08:03.085 test director was the most experienced of the team, uh, 141 00:08:03.085 --> 00:08:05.685 having had 14 years of experience on the MQ nine. 142 00:08:06.605 --> 00:08:09.545 And in 13 of those years was a certified test director. 143 00:08:10.125 --> 00:08:13.005 So literally, this person had hundreds of, uh, 144 00:08:13.015 --> 00:08:15.485 tests done on the MQ nine at that field. 145 00:08:17.855 --> 00:08:20.415 MTE one though was fairly new to the MQ nine. 146 00:08:21.115 --> 00:08:24.175 Um, she, although she's had, uh, uh, other 147 00:08:24.685 --> 00:08:27.015 test experience primarily at Edwards Air Force Base 148 00:08:28.405 --> 00:08:31.385 in her first year at Edwards, she was a a, an intern.

149 00:08:32.405 --> 00:08:34.065 And then for the next six years 150 00:08:34.065 --> 00:08:37.705 after that, she was an instrumentation engineer working on 151 00:08:37.705 --> 00:08:39.145 the F 35 aircraft. 152 00:08:40.705 --> 00:08:44.045 Uh, MTE one was, at the time of this accident, 153 00:08:44.225 --> 00:08:47.645 was being trained to be upgraded to a test director. 154 00:08:48.525 --> 00:08:52.105 And the, uh, mishap test director was her primary trainer. 155 00:08:54.505 --> 00:08:56.245 The rest of the test team were composed 156 00:08:56.245 --> 00:08:59.315 of other aircraft maintainers, test engineers 157 00:08:59.615 --> 00:09:00.795 and weapons maintainers. 158 00:09:00.795 --> 00:09:01.195 Mm-Hmm. 159 00:09:06.245 --> 00:09:09.145 So their, their safety plan identified three 160 00:09:09.255 --> 00:09:10.795 hazards shown here. 161 00:09:12.955 --> 00:09:16.095 And the Safety Review Board assessed the test as low risk. 162 00:09:18.075 --> 00:09:19.205

Note that this, uh, 163 00:09:19.785 --> 00:09:22.925 low risk assessment was the original risk assessment 164 00:09:23.615 --> 00:09:25.715 and did not account for changes to the test 165 00:09:25.715 --> 00:09:27.475 that I will talk about in the next slide. 166 00:09:32.925 --> 00:09:36.165 So the test procedure test procedure called 167 00:09:36.185 --> 00:09:40.785 for a spectrum analyzer to measure the, 168 00:09:40.805 --> 00:09:42.385 the telemetry readings from those weapons. 169 00:09:43.545 --> 00:09:46.345 Normally, the spectrum analyzer would be placed on a table, 170 00:09:46.885 --> 00:09:49.235 um, away from the aircraft, 171 00:09:50.805 --> 00:09:52.755 but for some reason, um, 172 00:09:53.305 --> 00:09:56.755 that spectrum analyzer wasn't available due 173 00:09:56.755 --> 00:09:57.875 to the calibration issue. 174 00:09:59.125 --> 00:10:02.065 So not wanting another delay, test director 175 00:10:02.085 --> 00:10:05.545 and, uh, semi maintainers went to, to the tool crib to, uh,

176 00:10:05.975 --> 00:10:07.425 look for an alternate method. 177 00:10:08.745 --> 00:10:11.525 And so they found this radio frequency power meter. Mm-Hmm. 178 00:10:11.595 --> 00:10:14.565 It's a handheld device that, uh, with a picture shown there. 179 00:10:15.975 --> 00:10:18.465 They found that, and a test director who, 180 00:10:19.715 --> 00:10:23.675 although was unfamiliar with that device, um, er determined 181 00:10:23.675 --> 00:10:26.155 that it would serve the, the need for the test. 182 00:10:28.095 --> 00:10:31.555 So on that night, um, there was some more aircraft issues 183 00:10:31.555 --> 00:10:34.595 that, uh, ultimately resulted in the test being canceled. 184 00:10:36.095 --> 00:10:40.035 Uh, and so since the, uh, test director was, uh, uh, 185 00:10:40.215 --> 00:10:43.035 fairly unfamiliar with the handheld device, he took 186 00:10:43.035 --> 00:10:45.355 that opportunity to take measurements on the aircraft. 187 00:10:45.855 --> 00:10:49.025 He went to the right side of the aircraft, um, 188 00:10:49.175 --> 00:10:50.465 took some readings from the weapons, 189 00:10:51.415 --> 00:10:55.345

and then walked back towards the back of the aircraft 190 00:10:55.345 --> 00:10:58.785 around the propeller and to the left side of the aircraft, 191 00:10:58.805 --> 00:11:00.185 and took some readings there as well. 192 00:11:01.175 --> 00:11:02.755 And he did that multiple times. 193 00:11:04.935 --> 00:11:08.395 All the while, um, the MTE one was observing this 194 00:11:09.055 --> 00:11:10.385 because she was told 195 00:11:10.385 --> 00:11:13.745 that she would be the one performing this task 196 00:11:15.045 --> 00:11:16.465 for the test the following night. 197 00:11:21.225 --> 00:11:24.375 There was some, uh, witnesses, uh, observing this, uh, 198 00:11:25.075 --> 00:11:26.455 uh, this practice. 199 00:11:27.235 --> 00:11:29.695 And so, uh, one of 'em, uh, testified 200 00:11:29.695 --> 00:11:32.815 that they heard the discussion that, uh, 201 00:11:33.525 --> 00:11:37.135 this device had to be placed about six to 12 inches 202 00:11:37.135 --> 00:11:39.175 behind the weapon in order to collect the data.

203 00:11:41.435 --> 00:11:42.965 This was contradictory to 204 00:11:42.995 --> 00:11:45.605 what the test director later testified. 205 00:11:46.565 --> 00:11:50.265 Um, when he said that he instructed MTE one 206 00:11:50.605 --> 00:11:53.965 to take the readings at the wingtips were in front 207 00:11:53.965 --> 00:11:55.045 of the weapon stations. 208 00:11:56.635 --> 00:11:58.975 And oh, by the way, he, he also mentioned that, uh, 209 00:11:58.995 --> 00:12:02.505 he instructed the, uh, engineer to check in 210 00:12:02.505 --> 00:12:04.585 with the crew chief prior to approaching the aircraft. 211 00:12:10.785 --> 00:12:12.645 So on the day of the accident, uh, 212 00:12:13.485 --> 00:12:17.275 there's a configuration log that was, uh, used 213 00:12:17.275 --> 00:12:20.275 to document the change in the use of the 214 00:12:20.975 --> 00:12:23.175 handheld power meter instead of this, instead 215 00:12:23.175 --> 00:12:24.335 of the spectrum analyzer. 216 00:12:25.325 --> 00:12:28.305

But the test safety plan was not reevaluated 217 00:12:28.325 --> 00:12:30.905 for any new risk due to this procedure change. 218 00:12:33.965 --> 00:12:36.385 So in the afternoon, uh, the testing gathered again 219 00:12:36.385 --> 00:12:38.815 for their pre-test mission brief, um, 220 00:12:40.115 --> 00:12:43.575 and the A IB, uh, noted that 221 00:12:44.735 --> 00:12:49.535 there was a, there were some items 222 00:12:49.765 --> 00:12:53.335 that were, uh, listed in their operating instruction on 223 00:12:54.095 --> 00:12:55.705 what were required to be briefed. 224 00:12:56.495 --> 00:12:58.975 Um, but they noted that, uh, 225 00:13:01.125 --> 00:13:04.345 that a lot of these items were not briefed at, 226 00:13:04.405 --> 00:13:05.625 uh, during this day. 227 00:13:06.505 --> 00:13:09.565 So some of them were that, uh, there was no roll call taken 228 00:13:09.565 --> 00:13:12.235 during the brief, although the vast majority 229 00:13:12.235 --> 00:13:13.835 of the participants did attend the brief.

230 00:13:15.145 --> 00:13:17.125 Uh, there was no discussion of assigned roles. 231 00:13:17.755 --> 00:13:21.985 So it wasn't brief that MTE one was, was, uh, 232 00:13:22.935 --> 00:13:25.145 will need to approach the aircraft during the test. 233 00:13:26.475 --> 00:13:28.905 There was no discussion on the communications plan, 234 00:13:29.475 --> 00:13:30.825 which meant no one 235 00:13:30.825 --> 00:13:34.585 besides the test director, MTE one, 236 00:13:36.295 --> 00:13:39.395 and another test engineer identified as MTE two. 237 00:13:39.935 --> 00:13:42.115 So no one besides those three knew that the only way 238 00:13:42.115 --> 00:13:46.005 to communicate with MTE one was 239 00:13:46.005 --> 00:13:48.365 through text messaging on her personal cell phone. 240 00:13:50.365 --> 00:13:53.625 Uh, there was no brief of the aircraft keep out zones 241 00:13:53.625 --> 00:13:54.745 as required by the to, 242 00:13:56.005 --> 00:13:58.985 and there was no brief of any kind of a knock it off raise. 243 00:14:02.405 --> 00:14:04.665

So after the, uh, the pre-test mission brief, 244 00:14:05.125 --> 00:14:07.985 the test engineers gathered the ground control station. 245 00:14:08.985 --> 00:14:13.525 And again, MT one, who was also unfamiliar with the device 246 00:14:14.245 --> 00:14:18.095 discussed this, uh, device with her, with her trainer, 247 00:14:18.555 --> 00:14:19.735 the test director. 248 00:14:20.895 --> 00:14:23.635 And basically the test director told MT one, 249 00:14:23.635 --> 00:14:26.855 you're gonna do the same thing from yesterday. 250 00:14:30.225 --> 00:14:34.485 So, um, the test director directed MTE one to proceed 251 00:14:34.485 --> 00:14:37.845 to the aircraft for the first half of the test to observe 2.52 00:14:37.945 --> 00:14:42.645 for any unusual controlled surface or turret movements. 253 00:14:43.405 --> 00:14:47.745 Um, MTE two testified that he thought this was odd 254 00:14:47.745 --> 00:14:50.985 because normally all test engineers were in the ground 255 00:14:51.005 --> 00:14:52.965 control station and never at the aircraft. 256 00:14:56.495 --> 00:14:58.915 So engines was started around 4:50 PM

257 00:14:58.975 --> 00:15:00.755 and they did about an hour's worth of testing 2.58 00:15:00.895 --> 00:15:01.995 before they called it. 259 00:15:02.095 --> 00:15:04.755 Uh, they called for a lunch break. 2.60 00:15:04.755 --> 00:15:06.995 They basically completed the first half of their test. 261 00:15:07.455 --> 00:15:08.635 Uh, it was hot 2.62 00:15:09.095 --> 00:15:10.475 and all the temperatures were rising, 263 00:15:10.535 --> 00:15:12.155 so it was a good time to, to take a break. 264 00:15:19.195 --> 00:15:20.215 So after the te 265 00:15:20.225 --> 00:15:23.335 after the lunch break, they, uh, reassembled at 7:00 PM 266 00:15:24.765 --> 00:15:27.865 and then engine was started at around 7:36 PM 2.67 00:15:28.085 --> 00:15:30.305 around the time of evening civil twilight, 268 00:15:37.135 --> 00:15:40.315 uh, 7:51 PM the test director sends that text 269 00:15:40.335 --> 00:15:43.755 to MTE one indicating that it's time for her to go 270 00:15:43.755 --> 00:15:45.755

to the aircraft and take the readings. 271 00:15:46.955 --> 00:15:48.085 Shortly after that, 272 00:15:48.485 --> 00:15:51.365 MTE two leaves the ground control station just 273 00:15:51.365 --> 00:15:54.405 to check up on MTE one asked her if she was good to go 274 00:15:54.625 --> 00:15:55.725 and just, she said, yep. 275 00:15:57.025 --> 00:16:00.125 So MT one replies back to the test director saying, 276 00:16:00.125 --> 00:16:02.365 I'm walking through the aircraft right now, uh, 277 00:16:02.765 --> 00:16:07.085 which MTE two confirmed by sending that text that, that, uh, 278 00:16:07.435 --> 00:16:10.125 confirmed that she was putting on her hearing protection 279 00:16:10.545 --> 00:16:11.605 and grabbing the meter. 280 00:16:13.805 --> 00:16:15.695 Yeah, it took a little over a minute for her 281 00:16:15.695 --> 00:16:17.455 to walk from the ground control station to 282 00:16:17.455 --> 00:16:19.495 where the aircraft parking spot was at, 283 00:16:21.105 -> 00:16:24.725and she proceeded directly to the aircraft without stopping

284 00:16:24.785 --> 00:16:26.165 to check in with the crew chief. 285 00:16:27.255 --> 00:16:29.675 And, uh, no one, including the crew chief, 286 00:16:29.985 --> 00:16:31.395 stopped her at this point. 287 00:16:34.485 --> 00:16:36.785 As MTE one reached the aircraft, 288 00:16:37.915 --> 00:16:40.335 the crew chief radios the ground control station 289 00:16:40.475 --> 00:16:43.935 to ask if the KU link was on, presumably 290 00:16:43.935 --> 00:16:46.295 because he was concerned about the radiation hazard. 291 00:16:47.615 --> 00:16:51.155 Um, and the sensor operator replies with the affirmative. 292 00:16:58.955 --> 00:17:01.855 So there were some witnesses who, uh, were there also 293 00:17:01.855 --> 00:17:04.375 during the previous night that was the present at the, uh, 294 00:17:05.155 --> 00:17:07.575 at the aircraft during this, this night as well. 295 00:17:08.325 --> 00:17:11.265 And they said that they saw her basically do the same thing 296 00:17:11.265 --> 00:17:14.095 from the night before, which meant she went 297 00:17:14.095 --> 00:17:16.775

to the right side of the aircraft behind the weapon, 298 00:17:17.795 --> 00:17:21.585 took the readings, and then when she turned 299 00:17:21.645 --> 00:17:24.105 and started walking towards the rear of the aircraft, 300 00:17:24.965 --> 00:17:26.815 that was probably when others started waving 301 00:17:26.875 --> 00:17:28.775 and shouting to try to get her attention. 302 00:17:30.205 --> 00:17:31.305 But she was heads down 303 00:17:31.445 --> 00:17:33.745 and appeared to be pressing buttons on the device. 304 00:17:34.125 --> 00:17:37.455 And as confirmed by the A IB 305 00:17:37.455 --> 00:17:40.615 during a post-event demonstration, you can't hear anything 306 00:17:40.615 --> 00:17:42.575 besides engine noise in that location. 307 00:17:45.525 --> 00:17:49.895 So based on the engine readings, it was only seven seconds 308 00:17:50.065 --> 00:17:51.695 after reaching the aircraft 309 00:17:52.245 --> 00:17:54.615 that MTE one was struck by the propeller. 310 00:17:57.015 --> 00:17:58.235 As this was unfolding,

311 00:17:58.455 --> 00:18:00.755 the crew chief was yelling on the radio, kill, 312 00:18:00.785 --> 00:18:01.795 kill, kill, kill. 313 00:18:03.545 --> 00:18:07.365 And, uh, which meant that he was, uh, trying to get the, uh, 314 00:18:07.365 --> 00:18:09.205 the air crew to shut off the engine. 315 00:18:09.935 --> 00:18:11.465 However, as, 316 00:18:11.735 --> 00:18:14.585 because they were just talking about the KU link a few 317 00:18:14.585 --> 00:18:17.185 seconds ago, the air crew thought they, 318 00:18:17.405 --> 00:18:19.105 he was talking about the KU link. 319 00:18:19.125 --> 00:18:21.785 So they shut off the KU link, but not the engine. 320 00:18:23.055 --> 00:18:24.995 It was only 17 sec seconds 321 00:18:24.995 --> 00:18:29.605 after the strike that the air crew finally realized that 322 00:18:30.165 --> 00:18:31.865 the crew chief may have been talking about 323 00:18:31.865 --> 00:18:33.025 killing the engine instead. 324 00:18:33.025 --> 00:18:33.385

Mm-Hmm. 325 00:18:39.225 --> 00:18:41.605 So this was, these are the series of events. 326 00:18:41.615 --> 00:18:45.325 After the, after the strike, immediately there was a couple 327 00:18:45.325 --> 00:18:46.405 of 9 1 1 calls. 328 00:18:47.485 --> 00:18:51.065 Uh, there was an emergency response team located on the 329 00:18:51.065 --> 00:18:54.095 airfield that came to, came to the scene, 330 00:18:54.475 --> 00:18:59.065 and, uh, started, uh, uh, helping the MTE one. 331 00:19:00.675 --> 00:19:02.865 About 25, about 20 minutes later, 332 00:19:03.125 --> 00:19:05.505 the local para paramedics arrived on scene 333 00:19:06.445 --> 00:19:08.535 with some additional medical equipment. 334 00:19:09.795 --> 00:19:12.455 The medevac helicopter arrived on scene about 13 minutes 335 00:19:12.465 --> 00:19:15.665 later, and finally about an hour 336 00:19:16.115 --> 00:19:19.665 after the event, the MTE one was 337 00:19:20.425 --> 00:19:22.025 helicoptered out of the, uh,

338 00:19:22.225 --> 00:19:27.185 airfield towards the hospital in Lancaster life. 339 00:19:27.215 --> 00:19:30.185 Save lifesaving resuscitation began in the helicopter 340 00:19:30.285 --> 00:19:34.145 and continued, um, after when they arrived at the hospital 341 00:19:34.845 --> 00:19:36.825 and, uh, but to no avails, 342 00:19:37.045 --> 00:19:40.435 and she was, uh, pronounced deceased, uh, 343 00:19:40.635 --> 00:19:42.435 a little over an hour after the event. 344 00:19:49.335 --> 00:19:53.395 The A IB wanted a, uh, replication of the environment 345 00:19:53.945 --> 00:19:57.315 that was present that night in order to, uh, help understand 346 00:19:57.985 --> 00:20:00.195 what could have contributed to her fatal mistake. 347 00:20:00.655 --> 00:20:04.395 So, one, the left there is one of the two stadium lights 348 00:20:04.395 --> 00:20:05.835 that were around the aircraft. 349 00:20:06.845 --> 00:20:08.825 The aircraft is there on the right side. 350 00:20:09.155 --> 00:20:12.315 We're looking aft, we're looking at the aft side 351 00:20:12.315 --> 00:20:15.195

of the aircraft from, from the right side. 352 00:20:19.055 --> 00:20:22.585 This picture is taken from in front of the wing looking aft 353 00:20:23.485 --> 00:20:25.335 and, uh, as you, 354 00:20:25.335 --> 00:20:27.335 hopefully you can tell you can't see the spinning 355 00:20:27.335 --> 00:20:28.655 propeller in these conditions. 356 00:20:34.535 --> 00:20:38.735 So the DOD uh, maintains a list of human factors 357 00:20:40.185 --> 00:20:43.915 that can play a role in aircraft mishaps to help, uh, 358 00:20:44.575 --> 00:20:46.715 a's identify potential areas of assessment. 359 00:20:48.335 --> 00:20:51.825 This particular A IB I've identified 14 factors. 360 00:20:52.205 --> 00:20:53.665 The first seven are shown here, 361 00:20:54.315 --> 00:20:55.415 and I'll just, uh, pause 362 00:20:55.415 --> 00:20:56.615 here for a bit for you guys to read. 363 00:21:08.515 --> 00:21:09.495 Here's the next seven. 364 00:21:29.415 --> 00:21:31.235 So that was the, uh, that's the end

365 00:21:31.235 --> 00:21:32.275 of the report presentation. 366 00:21:32.695 --> 00:21:36.615 Um, if you guys have any thoughts on 367 00:21:36.615 --> 00:21:40.615 how you can improve your test program, um, if you'd like 368 00:21:40.615 --> 00:21:41.815 to share, please do so. 369 00:21:41.835 --> 00:21:43.895 And hopefully it'll benefit others in the audience. 370 00:21:53.825 --> 00:21:56.405 So here are some areas that I think, uh, you know, 371 00:21:56.425 --> 00:21:58.565 you should take a look at in your organization 372 00:21:59.495 --> 00:22:02.195 to see if there's something there that you can change 373 00:22:02.635 --> 00:22:06.985 or re-emphasize within your test operations to make, 374 00:22:07.045 --> 00:22:10.205 uh, to keep it safer. 375 00:22:16.395 --> 00:22:18.575 So if you want more detail, these are the links 376 00:22:18.575 --> 00:22:20.575 to the actual a IB report 377 00:22:21.035 --> 00:22:23.095 and also a news release regarding the incident. 378 00:22:24.275 --> 00:22:27.355

And, um, with that, I thank you for your attention. 379 00:22:27.385 --> 00:22:29.195 We'd be glad to answer any questions. 380 00:22:43.045 --> 00:22:44.125 I am Joel Baden from Bell. 381 00:22:44.265 --> 00:22:48.245 Um, I have read this accident, uh, the a IB report, 382 00:22:48.245 --> 00:22:49.445 at least that's on the, on the web. 383 00:22:50.435 --> 00:22:52.695 And, uh, one thing I noticed is, you know, 384 00:22:52.695 --> 00:22:54.925 comparative experience levels. 385 00:22:55.185 --> 00:22:57.885 You had a test director who was an instructor, had been 386 00:22:57.885 --> 00:23:00.165 for 14 years, pretty significant with that company. 387 00:23:00.605 --> 00:23:02.935 Someone who was not necessarily inexperienced, 388 00:23:02.995 --> 00:23:05.735 but didn't have time at Journal Atomics 389 00:23:05.735 --> 00:23:06.975 or with the, with the debt. 390 00:23:07.645 --> 00:23:09.625 Um, and so it was undergoing, uh, training. 391 00:23:09.845 -> 00:23:13.345So there's a definitely a experienced deficit there.

392 00:23:13.675 --> 00:23:16.145 We've got a very experienced person giving instructions that 393 00:23:16.665 --> 00:23:19.045 on reflection, of course, look open-ended, right? 394 00:23:19.175 --> 00:23:22.235 Why didn't they explain to go, uh, watch out 395 00:23:22.235 --> 00:23:23.875 for the tail rot, or, I'm sorry, tail rotor. 396 00:23:23.875 --> 00:23:25.515 I work in helicopters, the, the propeller. 397 00:23:25.935 --> 00:23:29.635 And, uh, so I, I worry about, you know, 398 00:23:29.635 --> 00:23:32.155 we talk about crew resource management, having a voice 399 00:23:32.155 --> 00:23:33.755 of the table speaking up when you 400 00:23:33.755 --> 00:23:34.795 see something that isn't right. 401 00:23:35.475 --> 00:23:38.095 And I noticed that, that this kind of reeks of that in a lot 402 00:23:38.095 --> 00:23:39.895 of cases, you had a last minute change. 403 00:23:40.575 --> 00:23:43.145 A lot of people trying to audible the play, 404 00:23:43.145 --> 00:23:44.545 figure out how are we gonna get it done? 405 00:23:44.705 --> 00:23:47.045

I think a lot of us have been there trying to do our best 406 00:23:47.045 --> 00:23:48.845 to do that, but no one stepped back 407 00:23:48.845 --> 00:23:51.205 and said, Hey, we just changed the rules of the game 408 00:23:51.745 --> 00:23:52.765 by changing our equipment. 409 00:23:52.845 --> 00:23:55.005 I think that was pretty evident in the a IB report. 410 00:23:55.585 --> 00:23:59.535 But I also see, um, potential, uh, what I would like 411 00:23:59.535 --> 00:24:01.135 to discuss more with anyone, honestly. 412 00:24:01.675 --> 00:24:03.335 Um, there's that experience deficit, 413 00:24:03.475 --> 00:24:05.455 but there's also other social norms 414 00:24:05.455 --> 00:24:06.895 that might keep us from speaking up. 415 00:24:07.295 --> 00:24:09.755 Example, a female in a group of males, right? 416 00:24:10.425 --> 00:24:12.805 Is that affecting our ability to speak up? 417 00:24:12.825 --> 00:24:14.245 Is that affecting anyone's ability 418 00:24:14.305 -> 00:24:15.605to speak up for those other people?

419 00:24:16.595 --> 00:24:18.215 So those are things i I concern with. 420 00:24:18.275 --> 00:24:20.855 Um, I know that's not really a question, but, um, 421 00:24:20.915 --> 00:24:23.095 and also i, I worry a little too about the, 422 00:24:23.635 --> 00:24:26.215 the normalization of deviation that we see. 423 00:24:26.475 --> 00:24:28.575 Uh, the crew chief obviously was very experienced 424 00:24:29.525 --> 00:24:31.945 and allowed that person to walk by. 425 00:24:31.965 --> 00:24:34.145 You know, we always joke if you, if you don't want anyone 426 00:24:34.145 --> 00:24:35.265 to question you, hold a clipboard 427 00:24:35.265 --> 00:24:36.345 and look like you know what you're doing, 428 00:24:36.805 --> 00:24:38.465 and no one's gonna ask you what's going on. 429 00:24:38.565 --> 00:24:40.065 But that's one of those things that's like, 430 00:24:40.365 --> 00:24:41.945 if you're walking into my danger zone, 431 00:24:42.245 --> 00:24:43.985 tackle first ask questions next. 432 00:24:44.475 --> 00:24:46.135

And in cases where you've got a tail rotor, 433 00:24:46.135 --> 00:24:48.095 and in cases where you've got a propeller that's turning 4.34 00:24:48.945 --> 00:24:51.795 that can I, I really think that can be the only solution. 435 00:24:52.325 --> 00:24:55.305 And so, so seeing, seeing those things are obvious in the, 436 00:24:55.305 --> 00:24:57.265 in the, in the Monday morning quarterback, the after play. 437 00:24:57.765 --> 00:25:01.065 Um, but I'm just curious what, you know, 438 00:25:01.065 --> 00:25:03.105 what the group thinks on, on how we address those 439 00:25:03.105 --> 00:25:04.425 before the next accident happens. 440 00:25:05.855 --> 00:25:07.435 Oh, thank you for the inputs. 441 00:25:15.995 --> 00:25:18.685 I've seen it with, uh, some, uh, some operations 442 00:25:18.685 --> 00:25:20.605 where you have a, um, a chain 443 00:25:20.625 --> 00:25:23.085 or a rope tied to you, so you can't go to, 444 00:25:23.115 --> 00:25:24.565 into the danger zone physically. 445 00:25:25.555 --> 00:25:28.225 Isn't this something that would've been considered

446 00:25:28.565 --> 00:25:31.545 or part of the operation that should be considered? 447 00:25:33.355 --> 00:25:36.335 So that's a, that's a question for each organization 448 00:25:36.335 --> 00:25:39.295 to answer if, if that's a, a viable method 449 00:25:39.395 --> 00:25:40.975 for, for your ops. 450 00:25:41.805 --> 00:25:44.955 Um, for me, so not, this is not the a IB anymore, 4.51 00:25:44.955 --> 00:25:46.035 this is just me personally. 452 00:25:46.415 --> 00:25:48.745 Um, people should have spoken up, 453 00:25:48.745 --> 00:25:49.905 people should have stopped her, 454 00:25:50.325 --> 00:25:52.265 and the crew chief should have stopped her. 455 00:25:52.895 --> 00:25:57.535 Um, the, um, 4.56 00:25:58.295 --> 00:26:00.655 MTE two that I mentioned a couple times during the brief, 457 00:26:01.155 --> 00:26:04.465 um, he was feeling there's something odd here. 458 00:26:04.605 --> 00:26:07.465 You know, one is, you know, he's, she's being sent out 459 00:26:07.465 --> 00:26:08.705

to observe the aircraft when 460 00:26:08.725 --> 00:26:10.145 that's not the normal procedure. 461 00:26:10.805 --> 00:26:15.205 And two is, you know, uh, the fact that she's getting close 462 00:26:15.205 --> 00:26:17.125 to the aircraft, which they normally don't do, 463 00:26:17.545 --> 00:26:19.005 you know, somebody should have spoke up. 464 00:26:40.495 --> 00:26:41.495 so, 465 00:26:44.665 --> 00:26:49.565 So, uh, for, uh, several years of my career, I was a, um, 466 00:26:50.065 --> 00:26:54.745 flight test lead for p threes, uh, which for anybody 467 00:26:54.805 --> 00:26:56.425 who knows Navy aircraft, there's a lot 468 00:26:56.425 --> 00:26:57.465 of propellers on those. 469 00:26:57.485 --> 00:27:00.345 And we used to talk about the blades of death all the time, 470 00:27:01.295 --> 00:27:02.595 and they keep out zones. 471 00:27:03.365 --> 00:27:06.305 And it occurred to me while I was listening to this 472 00:27:06.855 - > 00:27:10.105that we tend to think of unmanned vehicles

473 00:27:10.205 --> 00:27:11.745 as being more like toys. 474 00:27:12.995 --> 00:27:15.015 And we forget that they're aircraft 475 00:27:15.515 --> 00:27:19.815 and we need to treat them the same way that we treat, 476 00:27:20.685 --> 00:27:25.145 um, manned aircraft and identifying those hazards. 477 00:27:25.865 --> 00:27:28.085 And I was surprised when you started 478 00:27:28.655 --> 00:27:32.445 discussing not only the, the lack of safety risk for, 479 00:27:32.505 --> 00:27:33.605 for the blades of death, 480 00:27:33.745 --> 00:27:37.645 but also that there were no communication provisions, 481 00:27:38.145 --> 00:27:42.745 you know, no calm lines, uh, long wires for the crew chief 482 00:27:42.765 --> 00:27:45.105 and for everyone else, anybody walk working 483 00:27:45.105 --> 00:27:47.745 around the aircraft while it was operating. 484 00:27:48.285 --> 00:27:52.575 And, and I wonder how much of a contributing factor, uh, 485 00:27:52.925 --> 00:27:55.255 that was because it was an unmanned vehicle, 486 00:27:55.955 --> 00:27:59.455

and so we were treating it generally differently than we 487 00:27:59.455 --> 00:28:03.575 would, you know, I, um, I, the, the last 17 years 488 00:28:03.575 --> 00:28:08.175 of my career, I've been doing navy systems and, and, uh, um, 489 00:28:09.305 --> 00:28:11.325 and, uh, carrier landing systems. 490 00:28:11.545 --> 00:28:13.325 No one's on a flight deck without having 491 00:28:13.715 --> 00:28:17.875 some way to communicate. So, yeah, 492 00:28:18.295 --> 00:28:22.525 So, um, that attitude, you know, of, of, uh, 493 00:28:23.745 --> 00:28:25.685 not having the proper communications plan. 494 00:28:26.605 --> 00:28:28.185 You know, think about this, this is 495 00:28:29.275 --> 00:28:32.915 an E-M-I-E-M-C ground test, you know, as, as, um, 496 00:28:33.635 --> 00:28:34.835 probably a lot of you have experienced, 497 00:28:35.235 --> 00:28:36.765 that is a pretty boring test. 498 00:28:37.085 --> 00:28:41.025 Normally, um, it's considered low risk, 499 00:28:41.205 -> 00:28:43.025so maybe their guards were down, right?

500 00:28:43.415 --> 00:28:45.465 When you, when you're involved in a high risk test, 501 00:28:45.935 --> 00:28:48.625 everybody's, you know, antennas are up. 502 00:28:49.225 --> 00:28:51.485 But this is a, a low risk ground test. 503 00:28:51.835 --> 00:28:54.285 They've been trying to do this, um, multiple times 504 00:28:54.285 --> 00:28:55.325 during the past few weeks. 505 00:28:56.015 --> 00:28:59.505 Um, maintainers are probably just wanting to get the things, 506 00:28:59.845 --> 00:29:02.305 the, the test done so they can bed the aircraft down 507 00:29:02.305 --> 00:29:03.505 that night and go home. 508 00:29:04.045 --> 00:29:06.185 So all these things, you know, 509 00:29:06.185 --> 00:29:08.345 could have played a part in, in this accident. 510 00:29:12.415 --> 00:29:13.195 You go right into the 511 00:29:20.665 --> 00:29:25.635 Dave, while they're doing that, you can go ahead 512 00:29:25.635 --> 00:29:27.705 and answer question that's coming into the mic now. 513 00:29:28.455 --> 00:29:30.375

Sure. Uh, just one quick, I couldn't remember in the list 514 00:29:30.375 --> 00:29:32.935 of 14 items if terminology was one of 'em. 515 00:29:33.115 --> 00:29:35.815 Um, but that definitely stood out to me, uh, you know, 516 00:29:35.815 --> 00:29:38.215 as it's something in our company that we're trying 517 00:29:38.215 --> 00:29:40.615 to be very specific and, and train and practice to, 518 00:29:40.995 --> 00:29:42.935 and hold each other accountable to those words such 519 00:29:42.935 --> 00:29:44.175 as the kill, kill, kill, 520 00:29:44.175 --> 00:29:45.735 and knowing exactly what that meant. 521 00:29:45.735 --> 00:29:49.885 Correct. But I forget, was that on there or part of it? 522 00:29:49.885 --> 00:29:51.085 Um, I'm not sure actually. Okay. 523 00:29:51.085 --> 00:29:53.185 But yeah, that's, but something to point out that, 524 00:29:53.185 --> 00:29:57.735 that I know is, uh, that we know within this room 525 00:29:57.735 --> 00:30:00.335 and the organization, that words mean things 526 00:30:00.475 --> 00:30:02.855 and practicing that, uh,

527 00:30:02.855 --> 00:30:04.295 in your immediate actions is important.

528 00:30:04.635 --> 00:30:05.055 Thanks.